

**M/V ULTRA GALAXY**



**Main Particulars**

**Type:** GENERAL CARGO

**IMO:** 9449352

**LOA x B :** 124 X 21,20

**GRT:** 10.021

**DWT:** 13.802

**R.Owner:** SUN ALLIANCE K.K

**T.Manager:** JP ALLIANCE Shipmanagement Co. Inc

**Operator:** ULTRA BULK Shipping A/S

**Arrival:** 19/02/2018

**Departure:** 15/03/2018

**SHIP REPAIR REPORT**

**Reference:** RE01803

**SCOPE OF WORKS CARRIED OUT**

- \* Docking, undocking and provision of general services for repair works.
- \* **Hull treatment works:** HP washing, blasting SA 2 in spots, application of touch up coats on blasted areas, application of 1 full coat, repainting of marks and letters.
- \* Removal and refitting of tail shaft for inspection and further maintenance works. Renewal of stern tube seals.
- \* Dismounting and mounting of aft fixed-pitch propeller.
- \* Polishing of propeller.
- \* Renewal of anodes
- \* Overhauling of valves / overhauling of boiler valves.
- \* Thickness measurements
- \* Anchor and chains. Lowering, HP washing, calibration, painting.
- \* Renewal of steel in cargo hold n° 1 and 2, tank top of cargo hold n° 1, bilge tank and aft peak tank.
- \* Hatch cover rubber channels repair.
- \* Hath cover cleats renewal.
- \* Loading test of cranes
- \* Overhauling of M/E auxiliary blower
- \* Overhauling of one E/R fan motor
- \* Renewal of some ballast discharge pipes
- \* Renewal of full electrical wiring between the control cabin and electric motor of bow thruster.
- \* Polishing of bowthruster propeller
- \* Fresh water washing by rotative nozzle of cargo holds, application of two touch up coats and one full coat.