

**M/V GURES**



**Main Particulars**

**Type: GENERAL CARGO**

**IMO: 9277307**

**LOA x B : 118,55 x 15,20**

**GRT: 4.967**

**DWT: 7.890**

**Flag: PORTUGAL**

**R.Owner: GURES SHIPPING ( PORTUGAL)**

**T.Manager: NAVIERA SICAR ( SPAIN)**

**Operator: AMAZSA ( SPAIN )**

**Arrival: 09/01/2017**

**Departure: 06/02/2017**

**SHIP REPAIR REPORT**

**Reference: RE01701**

**SCOPE OF WORKS CARRIED OUT**

- \* Docking / undocking and provision of general services for repair works.
- \* Thickness measurements
- \* **Hull treatment works:** HP washing, mechanical grinding, application of two touch-up coats on FB, VS and top sides; two full coats on same surfaces, repainting of full set of marks and letters.
- \* Anchor and chains: Lowering, marking, HP washing; chains calibration: renewal of five chain lengths.
- \* Cleaning of chain lockers.
- \* Rudder: Clearance measurements, dismantling and refitting of rudder blade Repair of the rudder flap.
- \* Dismounting and refitting of propeller blades for Class Survey Inspection.
- \* Tailshaft. Measure and report tailshaft clearance.
- \* Tailshaft. Withdrawal for Class Survey Inspection.
- \* Overhauling of valves.
- \* Cleaning of sea chests.
- \* Cargo holds and hatch covers: Cleaning, blasting SA 1, touch-up with two coats and painting with two full coats.
- \* Supplementing of hatch cover landing pads.
- \* Bow thruster propeller. Dismounting gratings and painting of tunnel.
- \* Bow thruster propeller. Dismounting, revision, overhauling and refitting.
- \* Renewal of some pipes.
- \* Box cooler. Dismounting, packing renewal ,pressure test and mounting back.
- \* Some mechanizing works.
- \* Freefall lifeboat. Removal ashore for cleaning and painting