

# SHIP REPAIR DIVISION

# M/V THORCO CASSIOPEIA



### **Main Particulars**

Type: General Cargo Ship

**IMO:** 9217163

**LOA x B:** 142,69 x 18,29

**GRT:** 7.406 **DWT:** 10.610

R.Owner: Marmuna Schiffahrt Gmbh & Co. KG.

T.Manager: Marconsult Schiffahrt Gmbh & Co. KG

Operator: Marconsult Schiffahrt Gmbh & Co. KG

**Arrival:** 02/11/2016 **Departure:** 14/12/2016

### **SHIP REPAIR REPORT**

#### SCOPE OF WORKS CARRIED OUT Reference: RE01620

- \* Berthing at the wharfage. Provision of general services for repair works
- \* Leading job : Crankshaft replacement.
  - \* Erection and removal of stagings in Engine Room.
  - \* Protecting main engine for hotworks.
  - \* Remove handrails and deck for access and reinstallation after completion.
  - \* Remove piping from engine room roof and reinstallation after completion.
  - \* Remove insulations from exhaust pipe and turbocharger.
  - \* Remove beam from roof and reinstallation after completion the works.
  - \* Remove engine room floor plates, flywheel and Vulkan coupling.
  - \* Lift main engine, remove the crankshaft and move engine block aside.
  - \* Fabrication and supply sliding supports for crankshaft.
  - \* Fabrication and supply supports for supporting the engine block.
  - \* Take out the crankshaft and transport to the workshop.
  - \* Transport new crankshaft onboard and installation in position.
  - \* Supply and installation of new insulation for exhaust pipe and turbocharger.
  - \* Chock fast renewal.
  - \* Clean 9 water jackets and 9 cylinder liners
  - \* Refitting of all the elements previously dismounted.
  - \* Ultrasonic cleaning and pressure test of one lube oil cooler.
  - \* Full cleaning of engine room.
  - Yard's assistance in sea test.