

M/V VALBELLA



Main Particulars

Type: CEMENT CARRIER

IMO: 9064281

LOA x B : 113,5 x 17,80

GRT: 5.286

DWT: 9.146

R.Owner: OCC Oceania Cement Carriers

T.Manager: Essberger JT GmbH

Operator: Essberger JT GmbH

Arrival: 03/02/2017

Departure: 23/02/2017

SHIP REPAIR REPORT

SCOPE OF WORKS CARRIED OUT

Reference: RE01702

- * Docking / undocking and provision of general services for repair works.
- * **Hull treatment works:** HP washing, FB (flat bottom), slurry blasting SA 2 in spots, 2 T/U coats, 1 F/C. VS (vertical sides), slurry blasting SA 2 in spots, 2 T/U coats, 1 F/C. TS (top sides), slurry blasting SA 2 in spots, 2 T/U coats, 1 F/C. Painting of draft scales, names and symbols. Repainting of load line.
- * **Load test:** E.R. crane, lifeboats davits (2), accommodation ladder.
- * **Tailshaft:** Tailshaft clearance, Magnaflux checking.
- * **Stern tube seals renewal.** Aft liner machining.
- * **Fixed propeller:** Dismounting and mounting. Dye check. Superpolishing.
- * Rudder stock and pintle measurement
- * Renewal of great amount of pipes of different services.
- * Overhauling of valves.
- * **Anchor and chains:** Lowering, marking, HP washing, chains calibration Chains-remove and refit from /to bitter end.
- * **Steel renewal:** Aft peak tank, chain locker (5 tons), WBT 1 and 5 port, pipe tunnel (5 tons).
- * **Sea chests.** Grids to be removed, blasted and painted. Renewal of stainless steel studs. Renewal of anodes. Renewal of Cathelco anodes.
- * **Windlass repair.** Windlass forward clutch to be replaced
- * **Main Switchboard.** Cleaning and checking of connections.
- * **Circuits breakers AE N° 1 and 2.** Testing
- * **Boilers** Overhauling and pressure test of safety valves for Class.
- * **M/E F.O HEATER.** Cleaning, pressure test. Renewal of gaskets and insulation
- * **M/E Auxiliary Blower.** Maintenance works / overhauling the electric motor.
- * **Vacuum pump** Maintenance works / overhauling the electric motor.