

M/V AIGRAN D



Main Particulars

Type: Chemical Tanker

IMO: 9138408

LOA x B : 126,73 X 19,02

GRT: 6.875

DWT: 10.020

Flag: Netherlands

R.Owner: AIGRAN SHIPPING BV (Netherlands)

T.Manager: MARITIME PERFORMANCES B.V. (Netherlands)

Operator: De Poli Tankers BV (Netherlands)

Arrival: 13/02/2015

Departure: 27/02/2015

SHIP REPAIR REPORT

SCOPE OF WORKS CARRIED OUT

Reference: RE01506

- * Docking / undocking and provision of general services for repair works
- * Hull cleaning and SA-2 sandblasting in spots
- * Hull paint touch up (2 coats on FB, VS and Top sides)
- * Application of one Full coat on underwater areas and top sides.
- * Painting of marks, symbols, letters, draft marks, plimsoll discs, etc
- * Anchor and chains cleaning. Chains calibration.
- * Renewal of anodes on external shell.
- * HP freshwater washing, painting and vacuum test of 3 DB ballast tanks
- * To take measurements on tailshaft and rudder (flap and rudder stock).
- * Renewal of stern tube seals.
- * Propeller brushing
- * Renewal of a great amount of pipes of different systems.
- * Brake lining renewal of anchor winches
- * Overhauling of PS/SB lifeboats davits winches
- * Fuel Pumps Overhaul of Main Engine.
- * Renewal of insulation of main engine exhaust expansion.
- * Renewal of 9 camshaft bearings
- * Renewal of manifold crane flexible hoses.
- * Shaft generator overhaul.
- * Renewal of ventilation duct of galley exhaust fan.
- * Steel repair on cargo tanks, funnel deck and inside one ballast tank.
- * Steel repair on funnel deck.
- * Steel repair below FW coolers located in the Engine Room
- * Renewal of steel on monkey deck
- * Reaconditioning of navigation bridge windows
- * Cleaning and painting seachest and seachest grids